

**ACTON •
MICKELSON •
ENVIRONMENTAL, INC.**

LOG OF BORING

Facility: G-P Fort Bragg

Address: 90 W. Redwood Ave.
Fort Bragg, CA

MW-2.7

5175 Hillsdale Circle #100
El Dorado Hills, CA 95762

AME Project No.: 16017.08

Area No./ Description: Parcel 2, SE Corner of Resaw #5/Planar #1

Page 1 of 1

Drilling Company: RSI
Drilled By: Jose Molindes
Drilling Method: Direct Push/Hollow Stem
Boring Diameter: 2.25"
Sampling Method: Dual Tube

Location (East/North):
Ground Surface Elevation:
Water Depth (Date, Time): 8' (11/29/05 1101)
Casing Elevation:
Total Depth (feet): 14.5' BGS
Weather: rain

Drilling Started: 11/29/05 1040
Drilling Finished: 11/29/05 1125

Logged By: J.D. Matthey, R.G., C.E.G
Checked By:

Source: Original field notes

PID/FID: PID

| DEPTH (feet) | SAMPLE | | BLOW COUNTS | | SOIL DESCRIPTION SOIL NAME, COLOR, RELATIVE DENSITY OR CONSISTENCY, MOISTURE, PARTICLE SIZE RANGE, OTHER | GRAPHIC LOG | SOIL CLASS | WELL GRAPHIC | COMMENTS | FIELD PID READING (ppm) |
|-----------------|----------|-----------|--------------------|-----------|---|-------------|------------|-----------------|---|----------------------------|
| | INTERVAL | SAMPLE ID | BLOWS/6 IN. (N) | IN. REC'D | | | | | DRILLING RATE AND CONDITIONS, WATER DEPTH, BACKFILL | |
| 0 | | MW-2.7-1 | | 36 | ASPHALT. FILL - SILTY GRAVEL (GM), grayish brown (2.5Y 5/2), Medium Dense, Moist, 70% fine to coarse gravel, 1 cm clast, 30% fine sand. | | GM | | 1048 | 0 |
| 5 | | MW-2.7-5 | | 37 | FILL - SILTY SAND (SM), dark gray (2.5Y N4/), Medium Dense, Moist, 70% fine sand, 30% fines. light olive brown (2.5Y 5/6), Medium Dense, Moist, 70% fine sand, 30% fines. | | SM | | 1100 | 0 |
| | | MW-2.7-7 | | 48 | olive yellow (2.5Y 6/6), Medium Dense, Moist, Fill?, Moderately Well Sorted (Fine to Medium), Subangular to Subrounded 80% fine sand, 20% fines. Wet. | | | | 1101 | 0 |
| 10 | | | | 12 | | | | | | |
| | | | | | | | | | Boring Terminated Total Depth = 14.5' | |